

Total No. of Questions—8]

[Total No. of Printed Pages—3

Seat No.	
-------------	--

[5152]-147

S.E. (Electrical) (II Sem.) EXAMINATION, 2017

ELECTRICAL MACHINES

(2012 PATTERN)

Time : Two Hours

Maximum Marks : 50

- N.B. :—** (i) Answer Q. No. 1 or Q. No. 2, Q. No. 3 or Q. No. 4 or Q. No. 5 or Q. No. 6, Q. No. 7 or Q. No. 8.
(ii) Neat diagrams must be drawn wherever necessary.
(iii) Figures to the right indicate full marks.
(iv) Use of non-programmable scientific calculator is allowed.
(v) Assume suitable data, if necessary.

1. (a) Draw the neat connection diagrams and explain the OC and SC test on 1-ph transformer for finding voltage regulation and efficiency. [6]
(b) Explain the Scott connection for 3-ph to 2-ph power conversion. [6]

Or

2. (a) Why parallel operation of transformers is necessary ? State the conditions to be satisfied for parallel operation of 1-ph transformer. [6]
(b) A 500 kVa, 1-ph, 50Hz, transformer has efficiency of 90% both at full load and half load with unity power factor. Determine its efficiency at 75% of full load and power factor 0.8 lagging. [6]

P.T.O.

3. (a) Obtain the equations for armature torque, shaft torque and lost torque. [6]
(b) Sketch and explain 3-point starter. [6]

Or

4. (a) Draw the power flow diagram for DC motor and explain. [6]
(b) A 37.3 kW, 500V, DC shunt motor on full load runs at 1000 rpm has efficiency of 92%. It have $R_a = 0.25 \Omega$ and $R_{sh} = 250 \Omega$. Determine : [6]
(i) Full load line current
(ii) Full load shaft torque and
(iii) Starter resistance to limit starting current to 1.5 times the full load current.
5. (a) Explain the construction of 3-phase induction motor. [6]
(b) 3-phase, 50 Hz, 6-pole induction motor running at 960 rpm at full load and develops a torque of 160 N-m. The rotational losses are 300 W and that of the stator iron and copper loses are 1820 W. Calculate : [7]
(i) Output power
(ii) Rotor copper loss and
(iii) Efficiency at full load.

Or

6. (a) Obtain the relation between : [6]
(i) Starting torque/full load torque
(ii) Full load torque/max. torque.
- (b) A 50Hz, 8-pole, 3-phase induction motor has full load speed 720 rpm. Rotor resistance per phase = 0.01Ω and standstill rotor reactance is $0.1 \Omega/\text{ph}$. Find the ratio of full load torque to maximum torque and speed at which maximum torque occurs. [7]

7. (a) Explain the no load and blocked rotor test on 3-phase induction motor to determine equivalent circuit parameters. [6]
(b) Sketch and explain circle diagram. [7]

Or

8. (a) Explain the testing of 3-phase induction motor as per IS-325. [6]
(b) Draw the neat connection diagram and explain the operation of star-delta starter. [7]