

Total No. of Questions—8]

[Total No. of Printed Pages—4

Seat No.	
---------------------	--

[4657]-537

S.E. (Electrical) (II Sem.) EXAMINATION, 2014

ELECTRICAL MACHINES—I

(2012 PATTERN)

Time : Two Hours

Maximum Marks : 50

N.B. :— (i) Answer *four* questions.

(ii) Neat diagrams must be drawn wherever necessary.

(iii) Figures to the right indicate full marks.

(iv) Use of electronic pocket calculator is allowed.

(v) Assume suitable data, if necessary.

1. (a) Sketch and explain phasor diagram for 1-phase transformer at ON Load. [6]

(b) State and explain the conditions to be satisfied for parallel operation of 1-phase transformers. [6]

Or

2. (a) State and explain standard connections of 3-phase transformer. Write *one* application of each. [6]

P.T.O.

- (b) A 20 kVA, 440/220 V, 50 Hz, 1-phase transformer has core loss of 324 W and copper loss of 100 W at half load. Calculate :
- (i) kVA loading for max. efficiency.
- (ii) Maximum efficiency at p.f. = 0.8 lag. [6]
3. (a) Explain the speed control of D.C. series motor by flux control. [6]
- (b) A 500 V, 6-pole, D.C. shunt motor have arm. and field winding resistance of 0.5Ω and 250Ω respectively. It draws a full load current of 20 A from supply. If rotational losses are 900 W, calculate efficiency of motor. [7]

Or

4. (a) Draw the construction diagram of D.C. machine and explain each part. [9]
- (b) Sketch and explain torque-arm. current characteristics of :
- (i) D.C. shunt motor and
- (ii) D.C. series motor. [4]

5. (a) Compare squirrel-cage and wound rotor of 3-phase induction motor. [6]
- (b) Obtain the equation for torque under running condition for 3-phase induction motor. [6]

Or

6. (a) Obtain the relationship between :
- (i) T_{st}/T_{max}
- (ii) T_{FL}/T_{max} . [6]
- (b) 3-phase, 8-pole, 50 Hz induction motor running at a speed of 710 rpm at a certain load draws a power of 35 kW. The stator and rotor losses amount to be 1200 W and 600 W respectively. Calculate :
- (i) rotor copper loss
- (ii) lost torque
- (iii) efficiency of motor. [6]
7. (a) Sketch the phasor diagram and explain the induction motor as a generalised transformer. [6]
- (b) With neat connection diagram, explain no load and blocked rotor test on 3-phase induction motor. [7]

Or

8. (a) Sketch and explain the circle diagram indicating, full load current, o/p line, torque line, rotor Cu loss, stator Cu loss and fixed losses. [8]
- (b) Explain the operation of star-delta starter used for 3-phase induction motor. [5]