Total No. of Questions: 8]	SEAT No. :
P4938	[Total No. of Pages :2

[4959]-1079 **B.E.** (Electrical) (2012 Pattern)

(b): Robotic & Automation *Time* : 2.½ *Hours*] [Maximum Marks: 70] Instructions to the candidates: Neat diagrams must be drawn wherever necessary. Figures to the right indicate full marks 2) Use of logarithmic tables slide rule, Mollier charts, electronic pocket 3) calculator and steam tables is allowed. Assume suitable data, if necessary. 4) **Q1)** a) Define Degree of freedom and spatial resolution. [6] b) Explain translational transformation with example. [6] c) What are the different rules for establishing link coordinate frames. [8] OR **Q2)** a) Write the concept of yaw, pitch and roll. [6] b) Explain rotational transformation with example. [6] Show how to add two vectors represented in homogeneous coordinates c) with different scale factors. What is the scale factor of the result? [8] Derive rotation in the y-z plane and the z-x plane using the geometric *Q3*) a) approach. [8] Derive the rotation formula using vector technique. b) [8] OR Explain multiple reference frames in space. Draw sketches if necessary. [8] *Q4*) a) A point $[1;2;3]^T$ is desired to rotate around z axis by 60° and then around b)

y axix by -90°. Find the resultant point after rotation. [8]

P.T.O.

Q5)	a)	Explain relationship between transformation matrix and angular veloc	ity. [8]	
	b)	Explain joint position controls (JPC) with neat sketch.	[9]	
		OR		
Q6)	a)	Explain Jacobian for prismatic and revolute joint for manipulator desi	gn. [8]	
	b)	Explain resolved motion position controls (RMPC) with neat sketch.	[9]	
0 = \	,		.	
<i>Q7</i>)	a)	Explain servo-control system in detail.	[8]	
	b)	Explain underwater robot design with neat sketch.	[9]	
OR				
Q8)	a)	Explain parts sorting robot with neat sketch.	[8]	
	b)	Explain selection criteria for sensors used, drives and actuators used manipulator design.	l in [9]	