



4766

BOARD DIPLOMA EXAMINATION, (C-14) OCTOBER/NOVEMBER-2018 DMNG-SIXTH SEMESTER EXAMINATION

MINE SAFETY ENGINEERING

Time: 3 Hours] [Total Marks: 80

PART-A

3X10=30

Instructions:

- 1. Answer **All** questions.
- 2. Each question carries **Three** marks.
- 3. Answer should be brief and straight to the point and shall not exceed five simple sentences.
- 1. Define the term unsafe conditions.
- 2. Define the pit safety committee.
- 3. Define the term Accidents.
- 4. List direct losses (costs) and indirect losses (costs) due to accidents in mines.
- 5. List the prevention of accidents due to haulage.
- 6. State the purpose of vocational training.
- 7. State the purpose of smoke helmet.
- 8. Define resuscitation.
- 9. List various miners' diseases.
- 10. Define the term pneumoconiosis.

PART-B

10X5=50

Instructions:

- 1. Answer any **Five** questions, choosing at least one from each section.
- 2. Each question carries ten marks.
- 3. Answer should be comprehensive and the criterion for valuation is the content but not the length of the answer
- 11. Explain about safety conferences and their objectives.
- 12. Explain the role of D.G.M.S safety in mines.
- 13. List the causes and remedial measures of accidents due to winding.
- 14. List the causes and preventions of accidents due to electricity in mines.
- 15. State the duties and responsibilities of training officer.
- 16. Explain the constructional details of compressed oxygen self contained breathing apparatus.
- 17. Explain about various forms of pollution due to mining.
- 18. State the cause, symptoms and precautions against Asbestosis.

/4766 2 SB3(T)-PDF